



OPTION 1



NOTES:

1. SEAM MATTING SURFACES: SWEEP & THOROUGHLY CLEAN GeoTough EPDM GEOMEMBRANE SURFACES PER CARLISLE SPECIFICATIONS. INSPECT ALL SURFACES TO ENSURE THAT STUBBORN DUSTING PARTICLES ARE REMOVED IN ANY CREVICES & FACTORY SEAM AREAS.
2. APPLY WEATHERBOND LAP SEALANT AT ALL INTERSECTIONS BETWEEN PRESSURE-SENSITIVE OVERLAYMENT STRIP.

GEOMEMBRANE & LINER ARE INTERCHANGEABLE TERMS

— GeoTough EPDM MEMBRANE - - - - NON-WOVEN GEOTEXTILE, MIN. 8 oz. MIN. /SY

	PRESSURE-SENSITIVE CURED OVERLAYMENT SEAM		SHEET NO.
			L-E2.1
1 SEE NOTE(S)	• L (LINER) • TL (TANK LINER)		